



Frank M. Ligon
Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

November 2004

TO: All U.S. Ford and Lincoln Mercury Dealers

SUBJECT: **Update: Supplement Announcement**
Customer Satisfaction Program 03M02 – Supplement #2:
New! *Certain 2000 - 2003 Model Year Focus Vehicles*
Additional Coverage for Front Coil Springs

REF: Customer Satisfaction Program 03M02 – Claims Update: Related Damage
Prior Approval dated June 11, 2003.

REF: Customer Satisfaction Program 03M02 – Supplement #1: Adjusted Labor Time
dated May 16, 2003.

REF: Customer Satisfaction Program 03M02: Certain 2000 Model Year Focus
Vehicles - Additional Coverage for Front Coil Springs, dated May 2003.

New!

PROGRAM TERMS

This program extends the coverage on the front coil springs to 10 years of service or 150,000 miles from the vehicle's warranty start date, whichever occurs first. This coverage will automatically transfer to subsequent owners. *If a vehicle already has more than 150,000 miles, this coverage will last until May 31, 2005.*

New!

VEHICLES COVERED BY THIS PROGRAM

Certain 2000 through 2003 model year Focus vehicles built at Wayne Assembly Plant from March 5, 1999 through January 13, 2003 and Hermosillo Assembly Plant from May 21, 1999 through April 27, 2003.

New!

REASON FOR THIS SUPPLEMENT

This bulletin is being re-issued to expand the model year coverage of Customer Satisfaction Program 03M02. Coverage within 03M02 is extended to certain 2000 through 2003 model year vehicles.

REASON FOR PROVIDING ADDITIONAL COVERAGE

In some of the affected vehicles, portions of the front coil springs may not have received adequate corrosion protection during the manufacturing process. Inadequate corrosion protection eventually may lead to a fracture of the spring. A spring fracture may result in suspension noise, possibly accompanied by sagging of one side of the vehicle. This is most likely to occur on vehicles operated for extended periods of time in high-corrosion areas of North America. Only a small percentage of the affected vehicles are expected to experience this concern.